

OPTEX FA **Instruction Manual**
Laser Line-shape Sensor
SHP Series

FOREWORD 2

SAFETY PRECAUTIONS 3

- Meanings of Safety Symbols 3
- Mandatory Requirements 3
- Cautions for Laser Product 4
- Precautions for Installation 5
- Operating Precautions 5

BASIC INFORMATION

BEFORE USE 6

- Parts Identifications 6
- Specifications 7
- Input/Output Circuit Diagram 9

INSTALLATION 10

- Sensor installation 10
- Measurement range and indicated value 11

OPERATING PROCEDURE.. 14

SETTINGS 15


- Main setting 15
- Mode setting, Separate parameter setting 16
- Teaching 18
- Sensitivity setting 20
- External Input Setting 20
- Remote Bank Swith 21
- Setting Initialization 21
- Communication 22
- List of Main setting menu options 23
- Separate parameter setting and range for the detection modes 24

ANALOG OUTPUT 26

- Peak detection mode/ Bottom detection mode/ Peak-to-peak detection mode/ Position Z mode 26
- Position X mode 26
- Span adjustment 27
- Offset 27




APPENDIX 28


- Operating Display Block Diagram 28
- Hold Function Timing Diagram 30
- Dimensional drawing 32
- Package Description 32
- Optionally available 32



OPTEX FA **OPTEX FA CO., LTD.**

93 Chudoji Awata, Shimogyo-ku Kyoto 600-8815 Japan
 TEL +81-75-325-2920 FAX +81-75-325-2921
<http://www.optex-fa.com>





FOREWORD

Thank you for purchasing the Laser Line-shape Sensor SHP Series. We hope you are fully satisfied with this product and enjoy its performance. To ensure your satisfaction, please follow the instructions below.

- Carefully read this instruction manual and keep it for future reference.
- If you have any question about the instructions here or a request for replacing the lost instruction manual, contact the sales office or store where you purchased the product.
- The contents in this instruction manual are protected by copyright and all rights are reserved by OPTEX FA CO., LTD. The descriptions and information included in this manual shall not be copied nor reproduced to any other form.



This product cannot be used as a safety device to protect human body.

Warranty

Whereas all of our products are tested in accordance with the strict internal standard, a faulty unit may unexpectedly be distributed. If this is the case with your product, identify its status and contact the sales office or store where you purchased it.

- The warranty period shall be one(1) year after its delivery to the customer.
- If the failure results from a manufacturer's fault, the manufacturer will replace the product (by sending a substitute) without charge except the following cases:
 1. Failure due to any abuse or misuse
 2. Failure due to a cause other than the product
 3. Failure due to unapproved modification or repair
 4. Failure due to acts of God

This warranty is limited to the delivered product only.
This warranty shall not cover the secondary damage caused by the faulty product.

SAFETY PRECAUTIONS

Carefully read and understand the safety precautions before operation. They provide the important information to protect your health and property. Strictly follow this instruction manual, and do not apply any installing/operating procedure which is not described in this manual.

Meanings of Safety Symbols



WARNING

Indicates a possible hazard that may result in death or serious injury if the product is used without observing the stated instructions.



CAUTION

Indicates a possible hazard that may result in personal injury or property damage if the product is used without observing the stated instructions.

Mandatory Requirements



WARNING


- Do not stare into laser beam or point laser beam at eyes since it may damage the eyesight.
- If smoke or abnormal smell occurs, stop operation and turn power supply off. If the problem requires a repair, contact the sales office or store where you purchased the product.
- This product cannot be used as a safety device to protect human body.
- Use the service voltage specified in the specifications.
- Do not touch the main unit and cable with wet hands. It may cause electric shock.
- Use only the special amplifier unit and extension cable to connect the sensor head. Other unit/cable may cause an accident or a damage of the product.
- Do not connect/disconnect the connection cable, terminal board or wiring when the power is on.

Cautions for Laser Product

This sensor emits visible laser beam compliant with JIS C6802/IEC/FDA, laser safety standard Class 2 (II). The warning and description labels are attached to the side of the sensor body.

Laser type of this product


Type	Red Laser Diode
Wavelength	650nm
Output	1mW



This sensor is subject to the FDA laser standard when exported to U.S.A, and notified to CDRH (Center for Devices and Radiological Health). Contact the us for the further details.



Use of controls or adjustments or performance of procedures other than the specified herein may result in hazardous radiation exposure.



Precautions for Installation



Installing the unit in the following conditions may result in fire, electric shock or product damage.

- High humidity
- High temperature due to a direct sunlight, etc.
- Much dust
- Poor ventilation
- Static electricity
- Corrosive gas or flammable gas
- Exposure to water, oil, or chemicals
- Direct exposure to vibration or impact



- Do not apply electricity during wiring. Ensure that the analog output does not contact with other wiring.
- Avoid parallel wiring and placing in the same piping with high-voltage cable or power transmission cable, since they may cause noise resulting in malfunction. Keep the power and signal cords in short length.
- Do not pull or apply impact forcibly since it may cause product damage.
- When using switching regulator for power supply, ensure grounding the frame ground terminal.

Operating Precautions

- Do not use the sensor in transient state (i.e. during warm-up time) after power on (5 minutes).
- The sensor performance may depend on the individual unit.
- Wipe off dirt on the cover (glass) of the emitting/receiving parts using a soft cloth etc., at every operation since it may cause incorrect detection.



Operations other than specified herein may result in hazardous radiation exposure.




Direct impact on the cover (glass) of emitting/receiving parts may result in damage of the product.


BASIC INFORMATION BEFORE USE

Parts Identifications


Front



LCD display



Detection surface



Specifications

Main connection cable

Insulator color	Brown	12 - 24V DC
	Blue	0 V
	White	Hold release
	Purple	Bank input 1
	Orange	Bank input 2/ Remote teach
	Gray	Bank input 3/Synchronization input
	Black	Output(OUT) 2 ≤100mA
	Yellow	Output(OUT) 1 ≤100mA
	Red	Output(OUT) 3 ≤100mA
	Black	Shield wire
	White	Analog output 4 mA - 20 mA
	Green	Frame ground
Weight	Approx. 100 g	

Specifications

Main body

Model	NPN output	SHP-100CN
	PNP output	SHP-100CP
Detection range	Laser-receiving range	100mm ± 25 mm
		17 mm (Width)/75 mm (Distance) to 27 mm (Width)/125 mm (Distance)
Emission		0.3 mm x 32 mm (Width)
		Class 2 (II) Red Laser Diode (Wavelength 650 nm, max. output 1 mW)
Power supply		12 - 24V DC -5% +10%
Power consumption (Electric power)		120mA/24V max., 180mA/12V max., incl. analog output current
Linearity *1		±0.5% FS (Z direction)
Resolution *2		50 μm (Z direction)
Sampling cycle		33 ms max.
Control output		NPN/PNP open collector, 30 V/100 mA max. (Remain voltage: max. 1.8V) 3 outputs
Analog output		4 mA - 20mA Out of the measuring range: 24 mA (Load impedance: max. 300 ohms)
Load dependence		±0.05%
Temperature drift		±0.05% FS/°C
Warm-up		5 min max.
Indicator	Output indicator	Orange LED
	Laser emitting indicator	Green LED
Ambient light	Sunlight	10,000 lx
	HF lamp	3,000 lx
Operating temperature		-10 °C to +40 °C (No condensation)
Operating humidity		35 to 85%/RH
Storage temperature/humidity		-20 °C to +60 °C / 35 % to 95 %/RH
Bank		8 (switchable)
Window size		Selectable
Shock resistance		10 to 55 Hz DA 1.5 mm XYZ ea. direction: 2 H
Vibration resistance		50 G (500 m/s²)
Protection category		IP66
Material		Main unit: Zinc die-casting/PC, Emitting/receiving window: Glass
Weight		Approx. 250 g (Excluding attached cable)


*1 : Measuring object: white ceramic, IMG GAIN: 0

*2 : Measuring object: white ceramic at the center measurement distance, IMG GAIN: 0


Input/Output Circuit Diagram

NPN type


Input circuit (Bank input, Hold release)



Output circuit




Analog output circuit




PNP type


Input circuit (Bank input, Hold release)



Output circuit



Analog output circuit




INSTALLATION

Sensor installation




- Avoid the operator's eye height for unit installation.
- Install the unit before connecting the special amplifier. (Turn the power off before starting installation work.)

The detection surface (the side of the emitting/receiving parts) should be parallel to the target object. Adjust the spot to conform to the detection point.



Measurement range and indicated value



Z-direction indication


The distance indication refers the "0" point to the position of 75 mm distant from the sensor.

The unit is 0.01 mm (ex. "2500" = "25 mm").

X-direction indication


The indication is relative value referring to the center point of sensor as "1500."




In the center area (within 100 mm from the sensor front face), the indication 100 in variation is equal to 1 mm.



Peak detection mode


Indicates the distance between the peak point in the measurement range (i.e. the edge closest to the sensor) and the reference position.






Bottom detection mode

Indicates the distance between the bottom point in the measurement range (i.e. the edge farthest from the sensor) and the reference position.




Edge count mode

Indicates the number of the selected-type edge.



Peak-to-peak detection mode

Indicates the distance between the peak point and the bottom point in the measurement range.




Position X mode

You can select either of the following options:

- To indicate the X position of the selected-type edge.
- To indicate the distance (X-direction) between the two(2) specified edges.

Indicates the distance between the two(2) edges specified in "EDGENUM1."
 Example
 EDGENUM1: 2
 EDGENUM2: 4
 Indicates the distance (X-direction) between Edge 2 and Edge 4.
 If "0" is selected in "EDGENUM1," the position of the edge number selected in "EDGENUM2"




Position Z mode

Position Z mode

- You can select either of the following options:

- To indicate the Z position of the selected-type edge.

Indicates the distance between the two(2) edges specified in "EDGENUM1."
 Example
 EDGENUM1: 1
 EDGENUM2: 2
 Indicates the distance (Z-direction) between Edge 2 and Edge 1.
 If "0" is selected in "EDGENUM1," the distance from the reference position (Z-direction) of the edge number selected in "EDGENUM2" is displayed.






Shape comparison mode


Indicates the percentage of the portion of compared object that is contained in the deviation tolerance.

Deviation tolerance (Light blue)
 Contained in the deviation tolerance by 100%

Measured waveforms are displayed in yellow, and teaching waveforms are displayed in light blue.




OPERATING PROCEDURE



SETTINGS

Main setting


Main setting menu



Mode setting, Separate parameter setting




Mode setting

Main setting menu



Mode setting


Peak detection mode



When the mode setting is made, the setting values of separate parameter can be changed without changing the mode anymore. To allow this, press the "SET" button once on the Main setting menu to go on to the menu of Separate parameter setting mode, then change the setting values. When the mode is set again, the following setting values are reset to the initial values; upper/lower thresholds of OUT1 to OUT3, span value for 4mA, and span value for 20mA.

Separate parameter setting


Upper limit threshold (Purple line)



Press the \uparrow / \downarrow buttons to select the parameter. (OUT1 HI is selected in the figure.)




When the indication turns red, press the \uparrow / \downarrow buttons to change the value.




After selecting the value, press the O_{SET} button to return to the main menu.


In setting the upper/lower limit threshold, the threshold of the selected output is displayed.



Press the \uparrow / \downarrow buttons to select the parameter. (EDGE DEF is selected in the figure.)



When the indication turns red, press the \uparrow / \downarrow buttons to change the value.



After selecting the value, press the O_{SET} button to return to the main menu.

If the Edge mode is selected, the edge appears on the display with lines. The edge is subject to the edge type selected in "EDGEDIRC." (Rising edge is selected in the figure.) Rising edge appears in purple, and falling edge in light blue.


Teaching

The thresholds are specified for the three (3) types of open collector output (OUT1, 2, and 3) by teaching.

You can teach the form in the form comparing mode.


Peak detection mode/Bottom detection mode/Peak-to-peak detection mode

Main setting menu




Form comparing mode

Main setting menu




Edge count mode

Main setting menu




Position X mode

Main setting menu



Position Z mode

Main setting menu



Sensitivity setting


Automatic setting

When the main setting menu is displayed, press the EXIT button for 1.5 seconds and more.

The red and green output indicators light on alternatively, then the optimum sensitivity is automatically selected.

 Pressing the EXIT button while each operation menu is displayed returns the display to Main setting menu.

Main setting menu



Manual setting

Selecting [SENS] in the setting menu enables to set the sensitivity manually.

External Input Setting

By setting BANK and/or SYNC IN, the bank input 1, 2, and 3 function as follows:

Setting	BANK SYNC IN	0 - 7	8	9
External input	Bank input 1 (Purple)	Invalid	Bank input	Bank input
	Bank input 2 (Orange)	External teach input		Bank input
	Bank input 3 (Gray)	Invalid	Simultaneous input	Simultaneous input

Remote Bank Switch

When the bank input line is set as Bank Input (refer to "External Input Setting"), the bank switch is available via connection.

Bank No.	Bank Input 1 (Purple)	Bank Input 2 (Orange)	Bank Input 3 (Gray)
0	0	0	0
1	1	0	0
2	0	1	0
3	1	1	0
4	0	0	1
5	1	0	1
6	0	1	1
7	1	1	1

0	NPN	Unconnected or connect to +V.
	PNP	Unconnected or connect to 0V.
1	NPN	Connect to 0V.
	PNP	Connect to +V.

Setting Initialization

- 1 Select [SYSTEM], then press  and hold. Select [INITIALIZE], then press  and hold. The menu returns to the initial menu.

Main setting menu



"System" in Item setting menu




 Press and hold

 Press and hold

- 2 Turn OFF the sensor power.
- 3 With pressing  and , turn ON the sensor power.
- 4 The message "INITIALIZING" appears on the display, and the data is initialized (factory preset values).

Communication

- 1 With the designated connection cable (separately available), connect the sensor and your PC.
- 2 Select [SYSTEM], then press O_{SET} and hold. Select [PC LOAD/SAVE] and press O_{SET} and hold.



- 3 The message "PC LOAD/SAVE" appears in red in the display. This completes the setting.



The measurement function of sensor stops during communication. The measurement function restarts when the communication has completed.

- The communication speed is 57600 bps. To decrease the communication speed, set in [COMMUNIC]. The setting configuration is as follows:

COMMUNIC	1: 4800bps
	2: 9600bps
	3: 19200bps
	4: 38400bps
	5: 57600bps

- The communication is available without setting the sensor. To allow this, set the software installed in PC.
- For the communication software at PC side, contact us or our sales representative.

List of Main setting menu options

Indication on LCD	Function/setting description (Press O_{SET} to select the parameter. Press and hold O_{SET} for 1.5 sec. or longer to confirm the setting.)	Selectable value range	Default setting
MODE	Selects the values including threshold and edge, and switches the display mode on the LCD display. PEAK: measures the distance between the peak point in the measurement range (i.e. the edge closest to the sensor) and the reference position. BOTTOM: measures the distance between the bottom point in the measurement range (i.e. the edge farthest from the sensor) and the reference position. PK-PK: measures the distance between the peak point and the bottom point in the measurement range. SHAPE: compares the shape of the measured object. EDGE COUNT: counts the edge number. EDGE POS X: measures the edge position and interval in the X-direction. EDGE POS Z: measures the edge position and interval in the Z-direction.	*1	*1
TEACHING FUNCTION	Performs teaching. Adjusts the general settings.		
BANK:	Selects the bank number. 0-7 : Bank number 8 : Enables to set external input. 9 : Refer to the description in "External Input Setting."	0 - 9	9
SYNC IN:	Selects the synchronization input setting 0 : Captures image constantly while the synchronization input is OFF. 1 : Captures image when the synchronization input is switched from ON to OFF. 2 : Captures image constantly while the synchronization input is ON. 3 : Captures image when the synchronization input is switched from OFF to ON. 4 : No setting (Captures image independently).	0 - 4	4
SMPL/HLD:	0: Hold OFF 1: Hold ON	0 - 1	0
COMMUNIC:	Selects the communication rate ^{*3} 0: Communication OFF (Remote monitor is available.) 1: 4800bps 2: 9600bps 3: 19200bps 4: 38400bps 5: 57600bps	0 - 5	0
BANK COPY:	Copies the bank settings to another bank.	0 - 7	0
LCD VIEW:	Reverses the LCD display vertically. (Waveform is not reversed.) 0: Normal display 1: Reversed display (With external monitor, only the captured image is reversed.)	0 - 1	0
IMG GAIN:	Selects the sensitivity of the image sensor. ^{*4} 0: Normal 1 - 63: The measurement accuracy deteriorates with higher sensitivity.	0 - 63	0
SYSTEM	Locks the settings, or returns the settings to the factory preset values. LOCK PARAM: Locks/unlocks the settings. Under the locked condition, the set items are displayed in blue and cannot be changed. PC LOAD/SAVE: For PC configuration INITIALIZE: Returns all the settings to the factory preset values.		

*1: The operation display changes when the settings are confirmed. For parameter descriptions including the ranges and initial values, refer to "Separate parameter setting and range for the detection modes".

*2: When any of "0" to "3" is selected, "bank selection 3 input" is deactivated.

*3: Remote monitoring is not available with communication function.

The communication setting is as follows: Data length=8 bit, No parity, Stop bit=1 bit.

*4: Sensitivity setting is available for each bank.

Separate parameter setting and range for the detection modes

Parameter *4	Indication on LCD	Description	Peak detection mode		Bottom detection mode		Peak-to-Peak detection mode		Shape comparison mode		Edge count mode		Position X mode		Position Z mode	
			Setting range	Initial value	Setting range	Initial value	Setting range	Initial value	Setting range	Initial value	Setting range	Initial value	Setting range	Initial value	Setting range	Initial value
OUT1 upper limit threshold	OUT1 HI	OUT1 upper limit threshold (Longer distance side)	-200 to 5200	5200	-200 to 5200	5200	0 to 5200	5200	0 to 100	90	0 to 200	1	0 to 3000	3000	-200 to 5200	5200
OUT1 lower limit threshold	OUT1 LO	OUT1 lower limit threshold (Shorter distance side)	-200 to 5200	2600	-200 to 5200	2600	0 to 5200	1600	—	—	—	—	0 to 3000	1600	-200 to 5200	2600
OUT2 upper limit threshold	OUT2 HI	OUT2 upper limit threshold (Longer distance side)	-200 to 5200	2600	-200 to 5200	2600	0 to 5200	1600	0 to 100	80	0 to 200	1	0 to 3000	1600	-200 to 5200	2600
OUT2 lower limit threshold	OUT2 LO	OUT2 lower limit threshold (Shorter distance side)	-200 to 5200	2400	-200 to 5200	2400	0 to 5200	1400	—	—	—	—	0 to 3000	1400	-200 to 5200	2400
OUT3 upper limit threshold	OUT3 HI	OUT3 upper limit threshold (Longer distance side)	-200 to 5200	2400	-200 to 5200	2400	0 to 5200	1400	0 to 100	70	0 to 200	1	0 to 3000	1400	-200 to 5200	2400
OUT3 lower limit threshold	OUT3 LO	OUT3 lower limit threshold (Shorter distance side)	-200 to 5200	-200	-200 to 5200	-200	0 to 5200	0	—	—	—	—	0 to 3000	0	-200 to 5200	-200
Hysteresis	OUT HYS	Hysteresises of OUTPUT 1 to 3	0 to 200	5	0 to 200	5	0 to 200	5	0 to 100	5	—	—	0 to 200	5	0 to 200	5
Deviation tolerance	TOLER Z	Deviation tolerance	—	—	—	—	—	—	0 to 200	15	—	—	—	—	—	—
Window size *1	WINDOW	SUBWINDOW size setting	0 to 3	0	0 to 3	0	0 to 3	0	0 to 3	0	0 to 3	0	0 to 3	0	0 to 3	0
		0: 416x472 1: 320x472 2: 224x472 3: 128x472														
Sub sampling *2	SAMPLE	SUBSAMPLE mode setting in the X-direction	0 to 1	0	0 to 1	0	0 to 1	0	0 to 1	0	0 to 1	0	0 to 1	0	0 to 1	0
		0: SUBSAMPLE OFF 1: SUBSAMPLE ON														
Shutter time	SENS	Shutter time (sensitivity) setting of the image sensor	0 to 263	100	0 to 263	100	0 to 263	100	0 to 263	100	0 to 263	100	0 to 263	100	0 to 263	100
Edge direction	EDGEDIRC	Edge direction setting	—	—	—	—	—	—	—	—	0 to 1	0	0 to 1	0	0 to 1	0
		0: Rising edge 1: Falling edge														
Edge definition *3	EDGE DEF	Edge judgment threshold	—	—	—	—	—	—	—	—	0 to 1000	128	0 to 1000	128	0 to 1000	128
Edge number 1	EDGENUM1	Setting of edge 1	—	—	—	—	—	—	—	—	—	—	0 to 31	0	0 to 31	0
		0: Origin (Zero displacement point of X- or Z-direction) Other than 0: Edge number (counted from the X-direction origin)														
Edge number 2	EDGENUM2	Setting of edge 2	—	—	—	—	—	—	—	—	—	—	0 to 31	1	0 to 31	1
		0: Origin (Zero displacement point of X- or Z-direction) Other than 0: Edge number (counted from the X-direction origin)														
Span 4 mA	SPAN 4MA	Distance setting with the analog output 4 mA	0 to 5000	0	0 to 5000	0	0 to 5000	0	—	—	—	—	0 to 3000	0	0 to 5000	0
Span 20 mA	SPAN20MA	Distance setting with the analog output 20 mA	0 to 5000	5000	0 to 5000	5000	0 to 5000	5000	—	—	—	—	0 to 3000	3000	0 to 5000	5000
Offset	OFFSET	Analog output offset (It is preset to 12 mA)	0 to 1	0	0 to 1	0	0 to 1	0	—	—	—	—	0 to 1	0	0 to 1	0
		0: Default value 1: Offset														

*1 A smaller display size can increase the response speed.


*2 Selecting "1" allows the image sampling of every other pixel in X-direction. It lowers the accuracy but improves the response speed.

*3 Adjust the threshold when the unit cannot detect edges of the object. Selecting larger value will ignore small level differences.


*4 Every setting item can be set for each bank.

ANALOG OUTPUT

Peak detection mode / Bottom detection mode /
Peak-to-peak detection mode / Position Z mode



Position X mode



Span adjustment and offset setting are available as the peak detection mode.

The analog output is not available in the shape comparison mode and edge count mode.

Span adjustment

1 Select "SPAN 4MA."

Separate parameter setting



2 When the setting value is turned in red (adjustable), press to select "4 mA" for the output distance (indication), then press and hold to determine the setting.

3 As step 2, set "20 mA" as the output distance in "SPAN 20MA."

Offset

Specify the distance to apply the analog output 12 mA.

1 Place the detection object at the distance of the analog output 12 mA.

2 Select "OFFSET."

Separate parameter setting




3 When the setting value is turned in red (adjustable), press to select "1," then press and hold to confirm the setting.

If "0" is selected after performing offset, the setting returns to the default value.



APPENDIX

Operation Display Block Diagram

- : Press the UP/DOWN(↑/↓) buttons.
- : Press and hold the SET button for 1.5 sec. or longer.
Pressing the EXIT button returns the display to the main menu.




Hold Function Timing Diagram



30


Peak detection with the synchronization input ON



* Hold release input
NPN type: connect the hold release input line (white) to 0 V.
PNP type: connect the hold release input line (white) to + V.

31

Dimensional drawing



Package Descriptions

- Main unit
- Main connection cable
- Instruction manual
- Fixing screw:
 - M4 x 50 mm, 2 pcs
 - M4 nut, 2 pcs
 - Washer for M4, 2 pcs

Optionally available

- Remote console (Cable length: 3m)
- Communication cable
- Main connection cable (Cable length: 7m)